Bowman Trailer Leasing

Record of Annual Inspection

The inspector of this vehicle meets the qualification requirements contracted in D.O.T. rule 49 CFR section 396.19

10233 Governor Lane Blvd
P.O. Box 431 Williamsport, MD 21795-0733
P – (800) 638-6733
F – (301) 733-7674

Inspection Location: Morristown, IN
(Branch ID, City & State)

Unit #: 245816
MFG/Year Wabash, 07

Serial #: 1JJV532W37L099231
Date of Inspection: 9-10-15
(Month / Day / Year)

JG

OK	DEFECT	N/A	
X	[ ]	[ ]	Registration valid installed in Registration Holder. License Plate # P822676 State IN Expiration: N/A.
X	[ ]	[ ]	Conspicuity Tape sides, rear ICC Assembly and rear doors (top & bottom).
X	[ ]	[ ]	All Marker, Clearance, Stop/Turn, Flashers and License Plate Lights are operational. All Electric Harnesses are secured properly. Seven way plug properly secured.
X	[ ]	[ ]	All Front and side panels are free of holes or damage. Top and bottom rails, front top rails and lower Rails are free of damage, properly fastened to cross members, posts and panels.
X	[ ]	[ ]	ICC assembly is properly secured, step is secure and functional and has reflective tape installed. Taillights are functioning properly; rear doors close and lock properly and have reflective tape install top and bottom. Mud flaps and brackets are installed and secure.
X	[ ]	[ ]	Air Ride Suspension ✓ Spring Ride Suspension ____ Springs, Rebound bolts, U-Bolts, Equalizers, Radius Rods, are free of damage, excessive wear, Secure and free of defects. Air bags are intact, shocks are properly installed, free of excessive oil and Leaks, brackets are attached and secure.
X	[ ]	[ ]	Slider Rails are properly secured to the cross members, no gaps or broken welds. Slider Pins are prope Installed and engaged to the slider rails. Slider handle is properly secured. OEM Gussets are intact. Le Gear straight, braces intact, properly attached to Wing Plate and Cross Members handle in good cond and able to be properly secured.
X	[ ]	[ ]	All Glad Hand Grommets are free of tears and excessive wear. Glad hands are properly secured to the Panel/bulkhead; Airlines are secured by a slider return spring. All airlines are free of wear marks, cra And defects. Air tanks are properly secured and drained.
X	[ ]	[ ]	Brake adjustment checked, brake thickness measured, slack adjusters properly secured and operatio Manual____ or Auto Slack ✓ equipped. Spring brakes are not caged, are free of excessive rust a Corrosion. Brake Drums are intact, no excess wear or damage, free of oil and grease.
[ ]	[ ]	X	Optional equipment is functional (Lift Gate), batteries secured properly. Winches & straps properly se ed And in good condition. ____ COMMENTS
X	[ ]	[ ]	Tires matched (within 6/32nds tread depth), free of dry rot, cuts cord or belt exposure, properly infla All lug nuts properly secured, rims are free of cracks, damage, or excessive wear with no oil present o rms All hubs are in good condition with proper fluid levels.

	LEFT	RIGHT
Front axle brake thickness	60%	60%
Rear Axle Brake Thickness	60%	60%

TREAD DEPTH 32/NDS" Radial = R Radial Recap = RRC Bias Ply = B

POSITION	TREAD DEPTH	LBS	POSITION	TREAD DEPTH	LBS
LFO	12	420	RFO	6	100
LFI	10		RFI	9	
LRO	8		RRO	10	
LRI	14		RRI	12	

HUBOMETER 139334 Tire Size LP 22.5 RIM TYPE Hub Piloted

INSPECTED BY Anthony Porter
PRINT NAME

SIGNATURE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL INSPECTION REPORT IN ACCORDANCE WITH CFR 396.