Trailer Leasing

Record of Annual Inspection

The inspector of this vehicle meets the qualification requirements contracted in D.O.T. rule 49 CF- tion 396.19

10233 Governor Lane Blvd
P.O. Box 431 Williamsport, MD 21795-0733
P – (800) 631-6733
F – (301) 223-7674

Inspection Location: Gibsonville, N. C.
(Branch ID & State)

Unit #: 2552 RT
MFG/Year Great Dane 99

Serial #: 1GRAA0624YS020249
Date of Inspection: 6-19-15
(Month / Day / Ye

J6

OK	DEFECT	N/A	
X	[ ]	[ ]	Registration valid installed in Registration Holder. License Plate # 16-44617 State ME Expiration: 2-29-16
X	[ ]	[ ]	Conspicuity Tape sides, rear ICC Assembly and rear doors (top & bottom).
X	[ ]	[ ]	All Marker, Clearance, Stop/Turn, Flashers and License Plate Lights are operational. All ... tric Harnesses are secured properly. Seven way plug properly secured.
X	[ ]	[ ]	All Front and side panels are free of holes or damage. Top and bottom rails, front top ra... nd lower Rails are free of damage, properly fastened to cross members, posts and panels.
X	[ ]	[ ]	ICC assembly is properly secured, step is secure and functional and has reflective tape ... lled. Taillights are functioning properly; rear doors close and lock properly and have reflectiv... pe installed top and bottom. Mud flaps and brackets are installed and secure.
X	[ ]	[ ]	Air Ride Suspension ___ Spring Ride Suspension ✓ Springs, Rebound bolts, U-Bolts, Equalizers, Radius Rods, are free of damage, excessive ... r, Secure and free of defects. Air bags are intact, shocks are properly installed, free of exce... e oil and Leaks, brackets are attached and secure.
X	[ ]	[ ]	Slider Rails are properly secured to the cross members, no gaps or broken welds. Slider ... are properly installed and engaged to the slider rails. Slider handle is properly secured. OEM Gussets ... ntact. Landing Gear straight, braces intact, properly attached to Wing Plate and Cross Members handle ... ood condition and able to be properly secured.
X	[ ]	[ ]	All Glad Hand Grommets are free of tears and excessive wear. Glad hands are properly s... ed to the front Panel/bulkhead; Airlines are secured by a slider return spring. All airlines are free of wea... rks, chaffing And defects. Air tanks are properly secured and drained.
X	[ ]	[ ]	Brake adjustment checked, brake thickness measured, slack adjusters properly secured a... perational. Manual ___ or Auto Slack ✓ equipped. Spring brakes are not caged, are free of exc... e rust and Corrosion. Brake Drums are intact, no excess wear or damage, free of oil and grease.
[ ]	[ ]	X	Front axle brake thickness LEFT 6 RIGHT 6 / Rear Axle Brake Thickness 6 6
[ ]	[ ]	[ ]	Optional equipment is functional (Lift Gate), batteries secured properly. Winches & strap ... perly secured And in good condition.

COMMENTS

Tires matched (within 6/32nds tread depth), free of dry rot, cuts cord or belt exposure, p... ly inflated. All lug nuts properly secured, rims are free of cracks, damage, or excessive wear with no ... esent on rims. All hubs are in good condition with proper fluid levels.

TREAD DEPTH 32/NDS"

POSITION	TREAD DEPTH	LBS
LFO	10	1200
LFI	10	
LRO	10	
LRI	4	

Radial = R Radial Recap = RRC Bias Ply = B

POSITION	TREAD DEPTH	LBS
RFO	10	1200
RFI	10	
RRO	9	
RRI	9	

HUBOMETER 12683

Tire Size _____

RIM TYPE _____

INSPECTED BY _____
PRINT NAME

SIGNATURE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL INSPECTION REPORT IN ACCORDANCE WITH 49 CFR 396.