RECORD OF ANNUAL INSPECTION

TrL #259118

Ed Bischoff — INSPECTOR'S NAME

7-7-15 — DATE OF INSPECTION

BS+E — MOTOR CARRIER NAME

PO Box 433 — ADDRESS

Williamsport — CITY

Md — STATE

21795 — ZIP CODE

PbB74160 — VEHICLE IDENTIFICATION NUMBER

2041901 Maine

Hub0-223248

9-92 Pines — TYPE OF VEHICLE

Van — MODEL

VEHICLE COMPONENTS / RESULT OF INSPECTION

COMPONENT	PASS	FAIL
Brake Systems		
Service Brakes	75%	
Parking Brakes	✓	
Brake Drums	✓	
Brake Rotors		
Brake Hoses	✓	
Brake Tubing	✓	
Low Pressure Warning Devices		
Tractor Protection Valve		
Air Compressor		
Electric Brakes		
Hydraulic Brakes		
Vacuum System		
Coupling Devices		
Fifth Wheel		
Pintle Hooks		
Drawbar/Towbar Eye		✓
Drawbar/Towbar Tongue	✓	
Safety Devices		
Saddle Mounts		
Exhaust System		
Leaks		
Location		

COMPONENT	PASS	FAIL
Fuel System		
Leaks		
Caps		
Bolts / Brackets		
Lighting System		
Headlights	✓	
Turn Signals	✓	
Identification	✓	
Tail Lights	✓	
Stop Lights	✓	
Clearance	✓	
Reflectors	✓	
License Plate Lights (Rear)	✓	
Fifth Wheel		
Hazard Warning	✓	
Other		
Safe Loading Systems		
Parts	✓	
Condition	✓	
Protection Against Shifting Cargo	✓	

COMPONENT	PASS	FAIL
Steering Mechanism		
Steering Wheel Free Play		
Steering Column		
Front Axle Beam		
Steering Components	✓	
Gear Box		
Pitman Arm		
Power Steering		
Ball & Socket Joints		
Tie Rods and Drag Links		
Nuts	✓	
Steering System	✓	
Suspension		
U-Bolts	✓	
Spring Hangers	✓	
Axle Positioning Parts	✓	
Spring Assembly	✓	
Torque, Radius or Tracking	✓	
Frame		
Frame Members	✓	
Tire & Wheel Clearance	✓	
Adjustable Axle	✓	
Assemblies (Sliding Subframes)	✓	

COMPONENT	PASS	FAIL
Tires		
Treads	9/32	
Labeled "Not for Highway Use"		
Markings		
Mixed Tires on Same Axle	✓	
Flaps		
Regrooves	✓	
Repair Work		
Excess Load Limits		
Contact with *Vehicle*		
Leaks		
Other		
Wheels & Rims		
Lock or Side Ring	✓	
Wheels & Rims	✓	
Fasteners	✓	
Welds	✓	
Windshield Glazing		
Cracks		
Discoloration		
Vision Reducing Matter		
Windshield Wipers		
Inoperative		
Missing or Damaged Parts		

Notes:

I certify the accuracy and completeness of this inspection. This inspection complies with all the requirements of 49CFR parts 396.17, 396.21 and Appendix G.

Ed Bischoff — INSPECTOR'S SIGNATURE

7-7-15 — DATE