MOUNTVILLE 103778

M, FHWA & PA. INSPECTION FORM *TRAILER ONLY*

Trailer Tech Parts & Service Inc.
Leola PA. 17540, Ph. 1-888-461-3683

Date: 3-1-16 R.O. #: 103776 Unit #: 2621RT (A)
VIN #: 3H3V532C2WT008079
Make: Hyundai Yr.: 1998 License #: 1638799

CODE: ✓=PASSED, X=FAILED / NEEDS REPAIRS, O=NOT APPLICABLE

*** PM TRAILER ONLY * FILL OUT THE ENTIRE SECTION BELOW** >UPDATED PM STICKER: _____ <<<initials<<

CODE	REPAIRED	ITEMS CHECKED
✓		CLEARANCE / MARKER LIGHTS
✓		TAIL / PARKING, LICENSE PLATE LIGHT
✓		STOP LIGHTS
✓		LEFT CENTER / REAR TURN
✓		RIGHT CENTER / REAR TURN
✓		REFLECTORS - IF REQUIRED BY LAW
✓		CONSPICUITY TAPE - SIDES & REAR
✓		GLAD HANDS - SECURED PROPERLY
✓		GLAD HANDS GROMMETS, LEAKING/TORN
✓		LIGHT PLUG PRONGS / FRONT END BOX
✓		LIGHT PLUG LID / SPRING WORKING
✓		LANDING LEG OPERATION LEFT/RIGHT SIDE
✓		LANDING LEG BRACES, WING BRACKETS
✓		LANDING LEG BRACE / WING WELDS
✓		CRANK HANDLE / HAND GRIP AREA
✓		CRANK HANDLE HOOK / HOLDER
✓		SAND SHOES - WORKING PROPERLY
✓		**GREASED ALL LANDING LEG ZERTS**
✓		AIR LINES & HOSES, no cracks, chaffing
✓		AIR VALVES - NO LEAKAGE
✓		AIR LINE SPRINGS & CLIPS - BOGIE AREA
✓		AIR TANK MOUNTING, NO LEAKS
✓		S-CAM BUSHING, WEAR CHECKED
✓		SLACK ADJUSTERS, PROPER TYPE
✓		BRAKE ADJUSTMENT, CHECKED STROKE
✓		**GREASED ALL S-CAM BUSHING ZERTS**
✓		**GREASED ALL SLACK ADJUSTER ZERTS**
✓		BRAKE SHOE RETURN SPRINGS, ROLLERS
✓		BRAKE CHAMBERS, NOT RUSTED OUT

CODE	REPAIRED	ITEMS CHECKED
✓		BRAKE LINING - NO CRACKS
✓		BRAKE DRUMS - WITHIN SPEC
O		ABS - WORKING PROPERLY, LIGHT OK

BRAKE LINING	CODE	REPAIRED	
LF= 16 /32	✓		WHEEL SEAL
LR= 18 /32	✓		WHEEL SEAL
RF= 13 /32	✓		WHEEL SEAL
RR= 18 /32	✓		WHEEL SEAL

CODE	REPAIRED	ITEMS CHECKED
✓		HUB OIL LEVELS CHECK / HUB CAPS OK
✓		HUB CAP GASKETS / HUB CAP PLUGS
O		GREASE TYPE HUB CAPS, NO LEAKAGE
✓		SLIDER LOCKING PINS, SPRINGS, ARMS
✓		AXLE - U BOLTS, MOUNTING PLATES
✓		AXLE SPRINGS, LEAF/AIR, REBOUNDERS
X	R	MUD FLAPS & BRACKETS
✓		RIMS (TIRE) NO CRACKS, WORN OUT
✓		LUG NUTS, NONE MISSING or LOOSE
✓		WHEEL STUDS, NONE MISSING
X	R	VALVE STEM CAPS > METAL ONLY <

TREAD DEPTH	PSI	TIRE TYPE
LFO= 12 /32	87 -PSI	R / B
LFI= 14 /32	98 -PSI	R / B
LRO= 9 /32	68 -PSI	R / B
LRI= 10 /32	99 -PSI	R / B
RFO= 10 /32	90 -PSI	R / B
RFI= 12 /32	97 -PSI	R / B
RRO= 8 /32	96 -PSI	R / B
RRI= 6 /32	0 -PSI	R / B

ALL TIRES AIRED TO PROPER>>PSI<<

ADDITIONAL TO COMPLETE THE FHWA / PA. INSPECTION > UPDATED INSPECTION STICKER: _____ <<<initials<<

CODE	REPAIRED	ITEMS CHECKED
X	R	**REGISTRATION CARD CURRENT
✓		**REGISTRATION CARD HOLDER
X	R	**LICENSE PLATE & STICKER CURRENT
		VIN PLATE ATTACHED, READABLE
		KING PIN - CHECK THE WEAR
		5th WHEEL PLATE - NO CRACKS
		5th WHEEL PLATE, PROPERLY ATTACHED
		RUN ON PLATE - OPERATIONAL
		TORQUE ARMS, MOUNTING BOLTS
		SPRING HANGERS & EQUALIZERS

CODE	REPAIRED	ITEMS CHECKED
		BOGIE "G" RAILS, NO CRACKS, HOLES
		AIR LINES PROPERLY SECURED - CLIPS
		SLIDER RAIL to "I" BEAM WELDS HOLDING
		AXLES, NO CRACKS, BENDS, DAMAGE
		WHEEL HUBS - NOT CRACKED, LOOSE
		WHEEL BEARINGS-PROPER WHEEL PLAY
		BOTTOM RAILS PROPERLY ATTACHED
		CROSSMEMBERS OPERATION
		ICC / REAR FRAME OPERATIONAL
		BODY WILL CONTAIN PRODUCT WITHIN IT

REPORT ANY DEFECTS THAT MAY RESULT IN A (D.O.T. FINE) OR PLACED (OUT OF SERVICE) ON BACK OF THIS FORM>>

"ALL BRAKE LINING & TREAD DEPTH MEASUREMENTS, TIRE PSI's ARE BEFORE ANY REPAIRS ARE COMPLETED."

Initial the repaired box AFTER the failed item is repaired, Additional SERVICES listed on back of this form>>>>>>

SERVICED / INSPECTED BY: Christopher J. Sowden EMPLOYEE #: 11

The Reynolds and Reynolds Company CC687801 O (03/09)