BOWMAN 266058

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
	266058
DATE 8/11/15	

PD

OR CARRIER OPERATOR: STB PALLET

RESS: 1348 S SECOND ST

, STATE ZIP CODE: PLAINFIELD NJ

OLE TYPE: ☐ TRACTOR ☐ TRAILER ☐ TRUCK , ☐ BUS ☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE): VAUGHN LEFF

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☐ YES

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER: 16-5268B

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

ITEM	OK	NEEDS REPAIR	REPAIRED DATE
1. BRAKE SYSTEM			
a. Service Brakes			
b. Parking Brake System			
c. Brake Drums or Rotors			
d. Brake Hose	✓		
e. Brake Tubing			
f. Low Pressure Warning Device	✓		
g. Tractor Protection Valve			
h. Air Compressor			
i. Electric Brakes			
j. Hydraulic Brakes			
k. Vacuum Systems			
2. COUPLING DEVICES			
a. Fifth Wheels			
b. Pintle Hooks			
c. Drawbar/Towbar Eye			
d. Drawbar/Towbar Tongue			
e. Safety Devices			
f. Saddle-Mounts			
3. EXHAUST SYSTEM			
a. Exhaust system leaking forward of or directly below the driver/sleeper compartment.			
b. Bus exhaust system leaking or discharging in violation of standard.			
c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle.	✓		
4. FUEL SYSTEM			
a. Visible leak.			
b. Fuel tank filler cap missing.			
c. Fuel tank securely attached.			
5. LIGHTING DEVICES			
All lighting devices and reflectors required by Part 393 shall be operable.			
6. SAFE LOADING			
a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway.			
b. Protection against shifting cargo.			
c. Container securement devices on intermodal equipment.			
7. STEERING MECHANISM			
a. Steering Wheel Free Play			
b. Steering Column			
c. Front Axle Beam and All Steering Components Other Than Steering Column			
d. Steering Gear Box			
e. Pitman Arm			
f. Power Steering			
g. Ball and Socket Joints			
h. Tie Rods and Drag Links			
i. Nuts			
j. Steering System			
8. SUSPENSION			
a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position.			
b. Spring Assembly			
c. Torque, Radius or Tracking Components			
9. FRAME			
a. Frame Members			
b. Tire and Wheel Clearance			
c. Adjustable Axle Assemblies (Sliding Subframes)			
10. TIRES			
a. Tires on any steering axle of a power unit.			
b. All other tires.			
11. WHEELS AND RIMS			
a. Lock or Side Ring			
b. Wheels and Rims			
c. Fasteners			
d. Welds			
12. WINDSHIELD GLAZING			
Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions).			
13. WINDSHIELD WIPERS			
Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.			
14. OTHER			
List any other condition(s) which may prevent safe operation of this vehicle.			

RUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, ____ REPAIRED DATE

IFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN RDANCE WITH 49 CFR PART 396.

ght 2012 J. J. KELLER & ASSOCIATES, INC.®
WI • USA • (800) 327-6868
m • Printed in the United States

ORIGINAL

2241
(Rev. 11/12)